
Reparatie pompa SP 5A-25

I.D.: 86737251

Data publicarii	05.09.23	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ:	8.535,00 RON - 8.535,00 RON
-------------------	-----------------------------

Descriere: Lucrari de reparatie pentru electropompa Grundfos tip SP 5A-25 care includ: manopera de demontare, constatare defecte si inlocuire piese: unitate pompare 1buc., termocupla 1buc., presostat FF 4-8 1buc., electrozi de nivel 3buc., vas de expansiune 750l, cablu 4x2,5 50ml.
