
Reparatie Advantest 9 REF 15299

I.D.: 58029833

Data
publicarii 15.06.21

Coduri CPV 50500000-0

Pretul
estimativ: 5.485,00 RON - 5.485,00 RON

Descriere: Service parte electronica presa Advantest C9842, SN 07002497 C7022/R09 inlocuire acumulator 2.6508.005.0 inlocuire EPROM si reprogramare firmware Vers. 1.24 verificare functionala a canalelor 1-2 verificarea finctionala a celor doua traductoare de deplasare trimise C7022/R02 inverter lampa display C7022/R04 LCD display
