

REPARATII PVC

I.D.: 67244048

Data publicarii	14.03.22	Coduri CPV	45421000-4
-----------------	----------	------------	------------

Pretul estimativ: 200,00 RON - 200,00 RON

Descriere: schimbat broasca pvc = 1 buc, maner ingust =2 buc, butuc BKS 90=2 buc, contrapiesa = 1 buc. Pretul include antemasuratori. mai putin
