
REPARATII MERCEDES SPRINTER BH70ANP

I.D.: 48737520

Data publicarii	07.08.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	1.342,70 RON - 1.342,70 RON
-------------------	-----------------------------

Descriere: Conditii neacceptate la termen: CONDUCTA AER (FURTUN INTERCOOLER),SCHIMB ULEI,FILTRU AER,FILTRU POLEN,FILTRU MOTORINA,FILTRU ULEI,ULEI GRUP,REPARAT ALTERNATOR
