

Serviciu inlocuit anvelope si echilibrat microbuz Mercedes Sprinter

I.D.: 42707222

Data publicarii	10.05.19	Coduri CPV	50116500-6
-----------------	----------	------------	------------

Pretul estimativ: 57,14 RON - 57,14 RON

Descriere: 1 serviciu inlocuit anvelope si echilibrat microbuz Mercedes Sprinter: pentru UM.01405 Muncelu - demontat+dejantat+echilibrat anvelope fata stanga: 1 buc 195/70 R16C - demontat+dejantat+echilibrat anvelope fata dreapta: 1 buc 195/70 R16C - demontat+dejantat anvelope spate stanga: 2 buc 195/70 R16C - demontat+dejantat anvelope spate dreapta: 2 buc 195/70 R16C
