

---

## **REPARATIE MIXER - HRS37/8-500-204/C-M80**

I.D.: 66149208

---

Data publicarii	10.02.22	Coduri CPV	50511100-1 50511000-0
-----------------	----------	------------	-----------------------

---

Pretul estimativ:	1.434,31 RON - 1.434,31 RON
-------------------	-----------------------------

---

Descriere: reparatie mixer HRS37/8-500-204/C-M80 (serie 638054). Costuri aferente transportului (dus - intors), constatare defect, inlocuire cablu si costul cablului ce urmeaza a fi inlocuit. Cost: 290,00 EURO + TVA Curs BNR: 1 euro = 4,9459 lei

---