

## Piese pompe

I.D.: 57876307

---

Data publicarii	10.06.21	Coduri CPV	42124000-4
-----------------	----------	------------	------------

---

Pretul estimativ:	37.808,00 RON - 37.808,00 RON
-------------------	-------------------------------

---

Descriere: 1. Reparata electropompa Grundfos tip SE 1.75.100.185.2 52S.H.N.51D nr. 9840079800000002- Etansare mecanica - Kit, Shaft Seal + L.Bearing FR52 2P A; 99718778 - Rulment - Kit, Shaft Seal + L.Bearing FR52 2P A; 99718778 - Rotor pompa - Kit, Impeller 97922824 F52; 98119521 - Kit o-ring - Kit, O-ring set for dry motor NBR; 98119450 2. Reparata electropompa Wilo tip Helix V 3602-4/16/E/S/400/50 nr. 418303/17W42/646531 - Etansare mecanica - SEAL-KIT-HELIX22-36-52 O/E; 4192148 - Rotor pompa / Labirint - Parte hidraulica completa HYD CPL,HELIX V3602-S-1,4307 KIT; 4237557 3. Reparata electropompa Grundfos tip S1.100.200.850.4.70H.C438.N.D.Z P/N 98539899 nr.472339P=90kW - Rulment - Kit bearings S Fr70 96294823 - Etansare mecanica primara - Kit , primary shaft seal 65 96567358 - Etansare mecanica secundara - Kit , secondary shaft seal 65 96567343 - Kit "O"-ring pt. motor - Kit , O ring motor / 96294825 - Kit "O"-ring pt. pompa - Kit , O ring pump / 96294826

---