
CUMPARARE DIRECTA

I.D.: 56737289

Data
publicarii 07.05.21

Coduri CPV

50800000-3

Pretul
estimativ: 520,84 RON - 520,84 RON

Descriere: Reparatie masina de tuns iarba VIKING, model MB 665 V, consta in schimb ulei si ascutit cutitul; Reparatie masina de taiat iarba VIKING, model MB 253.1 T, consta in schimb ulei si ascutit cutitul; Reparatie masina de taiat iarba Viking, model MB 253.1T, consta in filtru aer, schimb ulei, curatat carburator, ascutit cutit; Reparatie masina de insurubat MAKITA, consta in schimbarea mandrinei.
