

---

## Reparatie EP SMP 1000

I.D.: 43111160

---

|                 |          |            |            |
|-----------------|----------|------------|------------|
| Data publicarii | 12.02.20 | Coduri CPV | 50511000-0 |
|-----------------|----------|------------|------------|

---

|                   |                             |
|-------------------|-----------------------------|
| Pretul estimativ: | 2.715,47 RON - 2.715,47 RON |
|-------------------|-----------------------------|

---

|            |   |
|------------|---|
| Descriere: | Reparatie EP SMP 1000 - inlocuire rulment 6308, kit etansare, ulei - manopera |
|------------|---|

---