

Servicii de reparare regulator de turatie Woodward tip PGA, UG-8, UG-40

I.D.: 43014851

Documente participare:

- MetodologieEvaluare.doc 3.doc
- FisaDate_DF1077692.pdf
- 20200224_N_A_CSRegulatorWoodwardPGA_PGA58-02049.doc
- 20200224_N_A_CSRegulatorWoodwardUG8-02049.doc
- 20200224_N_A_CSRegulatorWoodwardUG40-02049.doc
- 20200224_N_A_Clauze contractuale-02049.docx
- 20200224_N_A_Fisa de date a achizitiei Woodward BUNA VERIFICATA-02049.doc
- 20200224_N_A_Formulare-02049.doc

Data publicarii	25.02.20	Coduri CPV	50531000-6
Termenul limita pentru depunere:	17.03.20	Pretul estimativ:	143.106,00 RON - 143.106,00 RON
Descriere:	Servicii de reparare regulator de turatie Woodward tip PGA, UG-8, UG-40		
