



Pachet servicii reparatii defecte constatate Hyundai Tucson

I.D.: 42668113

Data
publicarii

06.05.19

Coduri CPV

50112200-5

Pretul
estimativ:

2.041,22 RON - 2.041,22 RON

Descriere: Pachetul contine : racord flexibil esapament, garnitura esapament, senzor temperatura DPF, burduf planetara spate, simering grup spate, flansa grup spate, manopera aferenta inlocuirii acestora si reglaj directie .
