
Servicii de revizie tractor Same Explorer 105 DT E3

I.D.: 41448060

Data publicarii	09.01.20	Coduri CPV	50530000-9 50000000-5
-----------------	----------	------------	-----------------------

Pretul estimativ: 2.144,00 RON - 2.144,00 RON

Descriere: Serviciul de revizie a tractorului Same Explorer 105 DT E3 consta in reparatie sistem de franare fata stanga si cuprinde inlocuirea urmatoarelor piese de schimb: 0.027.4350.0 disc frana - 1 buc; 0.011.9551.0 disc frana cu striatii - 1 buc; 0.016.1031.2 bolt cilindru de directie fata stanga - 1 buc; 2.1519.078.0 oring timonerie schimbator de viteze - 2 buc.
Manopera 3 ore
