
Servicii de reparare si intretinere

I.D.: 102123897

Data publicarii	30.08.24	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 3.114,50 RON - 3.114,50 RON

Descriere: Reparatii tamplarie PVC: Inlocuit feronerie geam termoizolant = 1 buc x 210 ron Inlocuit broasca simpla usa interioara = 2 buc x 50 ron Inlocuit broasca Rotto usa exterior= 4 buc x 300 inlocuit maner usa = 6 buc x 48 ron inlocuit butuc usa = 6 buc x 55 ron Reglaj usi = 6 buc x 70 ron Inlocuit geam termopan =1.54mp x 225 ron Inlocuit zavor Rotto usa = 2 buc x 80 ron Inlocuit contrabroasca usa = 6 buc x 10 ron
