
Reparatie Pompa tip Wilo 1, 2 kw

I.D.: 73927220

Data publicarii 07.10.22

Coduri CPV

50511000-0

Pretul
estimativ: 3.780,00 RON - 3.780,00 RON

Descriere: Aprov.-Nasaud-nr.neces.459/07.10.2022- Reparatia consta in rebobinare si inlocuire tip etansari.
