

---

## **Inlocuire carcasa SEER 1000. Procedura se realizeaza la producator si sunt incluse calibrarari si**

I.D.: 84141786

---

Data publicarii	26.06.23	Coduri CPV	50800000-3
-----------------	----------	------------	------------

---

Pretul estimativ:	1.500,00 RON - 1.500,00 RON
-------------------	-----------------------------

---

Descriere:	Inlocuire carcasa SEER 1000. Procedura se realizeaza la producator si sunt incluse calibrarari si verificari
------------	--

---