
Servicii de reparatii masina de spalat si uscator rufe

I.D.: 51975855

Data publicarii	24.11.20	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 274,10 RON - 274,10 RON

Descriere: Servicii de reparatii masina de spalat si uscator rufe Reparat masina de spalat TEINER Verificare, demontat-montat garnitura hublou , reconditionat balama rama hublou, reglat microintrerupator,reglat presostat si probe functionale . Tarif =112.00 : Material=0.00 : Tarif =112.00 reparat uscator de rufe Candy Verificare ansamblului programator, reparat placa programator si rescriere soft, probe functionale. Tarif = 162.10 Material= 0 .00 Total =162.10
