

---

## **Reparatii pompa Flygt1.3 kw+Reparatii pompa 1.4 kw+Reparatii pompa 2 kw+Rep. pompa 3.5 kw,5kw s**

I.D.: 46783303

---

Data publicarii	28.05.20	Coduri CPV	50511000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 5.140,00 RON - 5.140,00 RON

---

Descriere: Reparatii pompa Flygt 1.3 kw:rebobinat ;lucrari mecanice conexe ;inlocuit semering ; presutupe; -Reparatii pompa cu tocator 1.4 kw(2 buc ):rebobinat ;schimbat rulmentii ;inlocuit presutupe ; cablu ; -Reparatii pompa cu tocator 2 kw : rebobinat ;schimbat rulmentii ;presutupe ; lucrari mecanice conexe -Reparatii pompa 3.5 kw (2 buc ):rebobinat ; schimbat rulmentii ; inlocuit presutupe ; esmering ; ulei -Reparatii pompa Wilo 5 KW : rebobinat ;schimbat rulmentii ;inlocuit presutupa ax;lucrari mecaanice conexe

---