

---

## Servicii de reparare a automobilelor

I.D.: 80916000

---

Data publicarii 10.04.23

Coduri CPV

50112100-4

---

Pretul estimativ: 1.181,00 RON - 1.181,00 RON

---

Descriere: hyundai tucson, NT 74 XPW, schimbat ulei si filtre, curatat dfp CF.DEVIZ  
NR.3836/05.04.2023

---