
Reparatie masina de spalat Uniqline, Indesit; uscator de rufe Candy

I.D.: 69828163

Data publicarii	02.06.22	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 768,15 RON - 768,15 RON

Descriere: Verificarea ansamblului, demontat-montat cuva, inlocuit rulmenti, probe functionale. Material = 26.94 Tarif = 265.00 Total = 291.9 Verificarea ansamblului , reconditionat placaprogramator, reglat intinzator curea si frobe functionale. Material = 25.00 Tarif = 191.00 Total = 216.00 Verificare, inlocuit pompa de apa. reglat presostat ,reconditionat electrovalva, recontidionat placa programator fara inlocuire de piese, probe functionale. Material = 25,21 Tarif = 235.00 Total = 260.21
