
Serviciu reparatie DACIA DUSTER A-3876

I.D.: 101797598

Data publicarii 21.08.24

Coduri CPV

50110000-9

Pretul
estimativ: 2.861,43 RON - 2.861,43 RON

Descriere: Serviciu reparatie DACIA DUSTER A-3876. Inlocuire injector, codare si calibrare sistem injectie.
