

---

## **Servicii de reparatie si inlocuire piese de schimb ecograf Hitachi Aloka F37 S/N: V0014910**

I.D.: 52703000

---

Data publicarii	14.12.20	Coduri CPV	50800000-3 50400000-9
-----------------	----------	------------	-----------------------

---

Pretul estimativ: 31.215,00 RON - 31.215,00 RON

---

Descriere: Modul RxBF Board, F37, EP557500 Manopera reparatie ecograf Hitachi Aloka F37 S/N: V0014910 - h - demontare modul CPU - reparatie monul procesor - inlocuit modul RxBF complet - verificare modul HV - testare sonde cu fantoma CIRS - curatare completa monitor, tastatura, balltrack

---