

Materiale reparatii

I.D.: 43207728

Data publicarii 11.06.19 Coduri CPV 44400000-4

Pretul estimativ: 5.011,06 RON - 5.011,06 RON

Descriere: rob 3/4=3*21.01,teav ppr 20=24*11.764,cot ppr 20*90=80*0.42,mufa ppr 20=14*0.336,racord ppr 20=32*4.20,vot ppr 20 fe=4*4.621,olandez ppr 20 fe=6*8.4,olan ppr 20 fi=7*7.14,clem ppr 20=60*0.294,ron ppr 20=13*8.4,rac 1/2 40=12*10.08,mufa br 1/2=4*4.2,teav pp 40*2m=8*6.72,teav pp 110*1m=4*3.36,teav pp 40*0,5=5*2.10,ram 40*67=8*2.1,cot pp 40*90=29*1.68,red 50*40=2*4.2,coliere 1 1/4=30*3.36,sif 20=1*18.49,sif 15=1*12.61,teav pp 75*1m=1*9.24,sif40=9*5.88,siolicon=4*13.44,bat st=3*50.42,bat leb=2*25.21,colt al=20*1.68,disc 230=15*8.4,elec 2,5=9*12.18,smieg=10*2.1,rect 40*40*2=84*8.82,capac 40=32*0.84,bronz 4l=2*96.64,grund 2,5=4*40.33,diluant1l=4*8.4,traf=4*12.6,gratar=4*3.36,pebsu=4*4.2,perie=1*26.89,canepa=1*2.52,pasta v=1*9.24,teflon=5*1.68,priza=1*10.92,teava pe 25=45*1.68,tur25=1*5.04,niplu=1*3.35,cot pe 25=2*5.04,rob 3/4=1*32.77,filtru 1/2=1*31.09,teava 110*2m=8*17.64,redus110-50=3*4.2,doza=1*5.88,comutat=1*8.4,stecher=2*10.08,teu pe 25=1*6.3,teflon=1*2.52,teava pp 50*2m=6*7.56,capac 110=1*3.36,aracet=1*10.08,var 15l=1*68.91,glet=1*15.13,butuc=1*25.21,sorb=1*15.97,racord pe 32=1*4.2,bat apa=2*25.21,sifon 50=1*25.21,rob 1/2=1*27.73,diblu 6=20*0.126,garn 1/2=10*0.126,red 1/2-3/8=4*2.52,teu ppr 20=6*0.588,teu ppr 20 fi=2*4.62,rezerv beta=2*69.75,vas wc=2*105.04,diblu wc=4*2.52,racord wc=2*23.53,mufa ec=2*5.46,psoar=2*117.64,rob pisor=2*37.81,sifon urinal=2*18.48,lavoat=2*107.56,consola=4*12.61,cot pp 50*45=4*1.68,redus40-50=4*1.26,mufa pp 50=2*3.36,mufa 110=2*4.2.....