
VW Transporter T6 - inspectie service cu schimb ulei, inlocuire placute frana fata si spate

I.D.: 70303835

Data publicarii 17.06.22

Coduri CPV

50112000-3

Pretul estimativ: 1.712,25 RON - 1.712,25 RON

Descriere: VW Transporter T6 - inspectie service cu schimb ulei, inlocuire placute frana fata si spate
