
Reparatie ecograf Philips CX50

I.D.: 101304879

Data publicarii	07.08.24	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ:	3.000,00 RON - 3.000,00 RON
-------------------	-----------------------------

Descriere:	Servicii de diagnosticare si reparatie ecograf CX50 cu seria SG52205017
------------	---
