



Inlocuit senzor de temperatura Autoclav Systec

I.D.: 34244096

Data
publicarii

01.02.19

Coduri CPV

30237475-9

Pretul
estimativ:

1.562,00 RON - 1.562,00 RON

Descriere: Reparatie autoclav Systec, conform referat nr.2726/30.01.2019 si raportul de interventie din data de 31.01.2019: Temperature Sensor PT 100A flexible standard=1buc si Manopera=2 ore.
