

Service SEM Hitachi SU8010

I.D.: 51963404

Data publicarii	24.11.20	Coduri CPV	45259000-7
-----------------	----------	------------	------------

Pretul estimativ: 7.500,00 RON - 7.500,00 RON

Descriere: Service recuperare SEM Hitachi SU8010 dupa pana de curent - pornire sistem de vacuum; - realizare backing coloana - aliniere mecanica coloana SEM - aliniere electromagnetica coloana SEM
