
Serviciu de reparatie Motofierastrau Stihl si polizor Makita

I.D.: 39930203

Data publicarii	30.08.18	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 745,40 RON - 745,40 RON

Descriere: Reparatia consta in: - constatarea defectiunii - identificarea pieselor defecte - inlocuirea pieselor defecte (capac demaror, buson ulei, buson rezervor, volanta, furtun, garnitura, maner de frana, fascicul fire, arc amortizor, buton, arc compresie, o-ring, stift blocare, carcasa mecanism) - testare/predare
