
Reparatie VW POLO

I.D.: 41837071

Data publicarii	05.02.20	Coduri CPV	50112000-3 50112100-4
-----------------	----------	------------	-----------------------

Pretul estimativ: 1.905,86 RON - 1.905,86 RON

Descriere: servicii de reparatii si de intretinere auto , respectiv : - intinzator curea 1 x 217.65 - curea transmisie 1 x 54.62 - releu 1 x 252.10 - fulie 1 x 252.10 - rulment alternator 2 x 29.41 - colector 1 x 33.61 - bujie 4 x 49.58 - bobina inductie 2 x 192.44 - manopera 10.80 ore x 42.02 lei / ora. Preturile nu contin TVA. Se acorda garantie conform legii AUTO VW POLO SSWWZZZ6RZGY072438
