



Servicii de reparatie Mercedes Benz Sprinter

I.D.: 96140585

Data publicarii	16.04.24	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	6.867,77 RON - 6.867,77 RON
-------------------	-----------------------------

Descriere:	Inlocuit Senzor impulsuri, set placute frana, senzor avertizare, set ambreiaj, volanta, set surub volanta
------------	---
