
Piese de schimb si reparatii automobil

I.D.: 73167582

Data publicarii	12.09.22	Coduri CPV	50112200-5
-----------------	----------	------------	------------

Pretul estimativ: 3.724,11 RON - 3.724,11 RON

Descriere: PIESE -FURTUN TURBOSUFLANTA 1 buc,268,91lei-GARNITURA CHIULOASA 1buc, 176,47lei - POMPA ULEI 1 buc, 630,25lei-SURUB CHIULOASA 1 buc,126,05lei-TACHETI HIDRAULICI 16 buc, 42,02lei, -CULBUTOR SUPAPA 16 buc, 63,03 lei-RACITOR ULEI MANOPERA 1 buc, 411,76 le - DEMONTAT MONTAT CHIULOASA 1 buc, 180lei, -REPARAT CHIULOASA 1buc, 250lei pentru automobil cu numar de inmatriculare SM-99-PRU. Rugam emitere factura electronica si transmitere prin sistemul national privind factura electronica RO e-Factura.
