

Reparatie motopompa Honda WB20XT

I.D.: 66123886

Data publicarii 08.02.22 Coduri CPV 34913000-0 50511000-0

Pretul estimativ: 200,16 RON - 200,16 RON

Descriere: 11217 BUJIE NGK BPR 6 ES BUC 1.0000 15.1261 15.13 2.87 18.00 19.00 VZ_19 0 2 2823611
Sfoara demaror 4.5mm ML 2.0000 3.3613 6.72 1.28 8.00 19.00 VZ_19 0 3 20632 ULEI 4T 10
W 30 LTR 0.6000 26.8908 16.13 3.07 19.20 19.00 VZ_19 0 4 99999901SP Curatat
carburator in baie de ultrasunete BUC 1.0000 29.4118 29.41 5.59 35.00 19.00 VZ_19 0 5
21248 SPRAY CURATITOR FRANE BUC 0.4000 16.8067 6.72 1.28 8.00 19.00 VZ_19 0 6
99999905SP Manopera reparatie utilaje 1 ORE 1.0000 126.0504 126.05 23.95 150.00 19.00
VZ_19 0