

---

## Reparatie pompa de spalat cu presiune HD 5/15

I.D.: 49738861

---

Data publicarii	14.09.20	Coduri CPV	34913000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 559,00 RON - 559,00 RON

---

Descriere: Reparatie pompa de spalat cu presiune HD 5/15. Reparatia implica schimbarea urmatoarelor piese de schimb: 6.961-000.0 - Microintrerupator 1 buc, 4.775-463.0 - pistol 1 buc, manopera- 1 buc

---