
30125000-1 Piese si accesorii pentru fotocopiatoare (Rev.2)

I.D.: 43340994

Data publicarii	26.06.19	Coduri CPV	30125000-1 30200000-1
-----------------	----------	------------	-----------------------

Pretul estimativ: 750,00 RON - 750,00 RON

Descriere: Reparatie fuser copiator Xerox M118 1. fuser pressure roller 2. fuser hot roller 3. fuser termistor, Sursa RPC 500W, 55000AB, 2x SATA, 2x PATA, 1x MB 20+4, 1x CPU 4pin, European Power Cord ,35 cm cables, 120mm Fan
