
REPARATIE autoambulanta VW Transporter

I.D.: 38859796

Data publicarii	03.10.19	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ:	1.210,00 RON - 1.210,00 RON
-------------------	-----------------------------

Descriere: REPARATIE autoambulanta VW Transporter: inlocuit supapa EGR si senzor presiune evacuare. Serie de sasiu WV1ZZZ7HZ8H125075
