
Servicii de reparare masina de spalat ind. Electrolux 33kg

I.D.: 93418355

Data publicarii	14.02.24	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.982,00 RON - 1.982,00 RON

Descriere: Reparatie masina de spalat rufe ind.Electrolux 33 Kg : inlocuit cablaj inverter protectie motor, inlocuit rezistenta electrica incalzire apa cuva; masini spalat rufe casnice 2 buc : montat si P.I.F. la DGASPC. SECTOR 1 / CSS. Odai
