
Reparatie insuflator electronic UI500

I.D.: 80423591

Data
publicarii 27.03.23

Coduri CPV

50421000-2

Pretul
estimativ: 8.960,00 RON - 8.960,00 RON

Descriere: Reparatie insuflator electronic UI500 G1 DEFECTIUNI CONSTATATE modul electronic joasa presiune defect. Regulator presiune defect. OPERATIUNI EXECUTATE demontare aparat, inlocuit modul joasa presiune, inlocuit regulator presiune, Calibrat senzori, efectuat calibrare touch screen, actualizat versiune soft, efectuat testare functionalitate si electrosecuritate
