
Necesar piese imprimante

I.D.: 38025627

Data publicarii	23.08.19	Coduri CPV	30125000-1
-----------------	----------	------------	------------

Pretul estimativ: 4.212,00 RON - 4.212,00 RON

Descriere: Canon IR6255i camera 207 - Display defect - necesar inlocuire 1782lei Canon IR6255i camera 402-404 pe Hol - Ansamblu motor reglare unitate cuptor defect - necesar inlocuire 190lei Panasonic KV-S3105C camera 512 - Necesari kit role preluare 1735lei Lexmark T642 camera 414 sn 7909TYY - Necesari kit role preluare hartie 100lei Lexmark T642 camera 419 - Necesari kit role preluare hartie 100lei Lexmark T642 camera 317B - Necesari kit role preluare hartie 100lei Lexmark T642 camera 317A - Necesari kit role preluare hartie 100lei Canon LBP6780 camera 2 Str. Traian - Necesari kit role preluare hartie 105lei
