
Servicii de reparare autocar BMC GL-11PVM

I.D.: 73912743

Data publicarii	03.10.22	Coduri CPV	50114100-8
-----------------	----------	------------	------------

Pretul estimativ: 4.530,23 RON - 4.530,23 RON

Descriere: Piесе: rulmenti interiori butuc roata - 2 bucati, rulmenti exteriori butuc roata - 2 bucati, butuc roata axa fata stanga. Manopera: deplasare x 4, inlocuit rulmenti butuci roti axa 1 si butuc roata axa 1 stanga, inlocuit furtun camera franare. Oferta se refera la autoutilitara de tip N3
