
Reparație aparat de spălat cu presiune Karcher

I.D.: 85254510

Data publicarii	26.07.23	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.304,91 RON - 1.304,91 RON

Descriere: Reparație aparat de spălat cu presiune Karcher: PISTON * (11K3) 4.553-319.3 GHIDAJ PISTON * 2.060-000.3 SUPORT DISC * (2M6) 5.116-381.0 SAIBA GHIDAJ * (12I8) 5.116-380.0 INEL * (4H5) 6.363-633.0 O-Ring 72c2mm * (4G3) 6.363-449.0 SET POMPA HDC * (1K3) 2.885-377.0 INTRERUPATOR (VECHI=6.961-000.0) * (12K2) 6.961-079.3 ARBORE DE COMANDA SET PIESE DE SCHIMB HDC * (1K1) 2.885-376.0 O-RING * 5.363-749.0 TIJA COMUTATOR * (5C) 5.107-313.0 MANOPERA, NORMA DE TIMP * UM
