
Servicii de reparare Hyundai Tucson cu nr. de inmatriculare CT24API apartinand A.P.I.A.Constanta

I.D.: 44389458

Data publicarii	29.10.19	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 473,69 RON - 473,69 RON

Descriere: Sevicii de reparatii constând in: -D/R aeroterma bord -curatat aeroterma bord -inlocuit filtru polen. Inlocuit: -filtru polen 1 buc. Total manopera 473,69 ron .
