

---

## Reparatie sistem climatizare Mercedes Sprinter

I.D.: 39934459

---

Data publicarii 14.08.18

Coduri CPV

50000000-5

---

Pretul estimativ: 879,52 RON - 879,52 RON

---

Descriere: Reparatie mufa PINI senzor clima si incarcare cu freon instalatie de climatizare Mercedes Sprinter

---