
Remediere defectiuni - Mercedes Actros SB14PDW

I.D.: 103040028

Data publicarii	16.09.24	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.610,00 RON - 1.610,00 RON

Descriere: Lucrari solicitate de client: SB14PDW - Remediere defectiune conectare telecomanda macara Constatari defectiuni : - Lipsa comunicatie radiofrecventa intre transmitator si receptor comunicatie. - Lipsa comunicare can-bus intre emitator si receptor. Denumire operatii executate/alte costuri : 1.Demontat cablaje si masurat cablaje. 2. Citire coduri de erori. 3. Demontat placa receptor si placa transmitator. 4. Verificare comunicare receptor si baza paltronic 5. Comunicare receptor si paltronic functional Manopera : 230ron + tva/buc x 7 buc = 1610.00 ron + tva Piese : 0.00 Total : 1610.00 RON + TVA
