
Reparatie la pompa Fireco de la autocpeciala Mercedes Sprinter MAI 35472

I.D.: 34676386

Data publicarii	20.03.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Termenul limita pentru depunere:	24.03.19	Pretul estimativ:	3.846,00 RON
----------------------------------	----------	-------------------	--------------

Descriere: Reparatie la pompa Fireco de la autocpeciala Mercedes Sprinter MAI 35472, dupa cum urmeaza: - 2 seturi piston cu segmenti, - 2 buc garnitura chiuloasa, - 1 buc demaror, - 2 buc modul aprindere, - 2 buc supapa admisie, - 2 buc supapa evacuare, - reparatie furtun presiune+ tambur,
