

## **Reparatie PERFUSOR COMPACT PLUS seria 14806, 14802, 14813 si INFUSOMAT COMPACT PLUS 4366**

I.D.: 91704013

Data publicarii 11.01.24 Coduri CPV 50000000-5 50420000-5

Pretul estimativ: 6.379,53 RON - 6.379,53 RON

Descriere: Reparatie PERFUSOR COMPACT PLUS seria 14806, seria 14802, seria 14813 si INFUSOMAT COMPACT PLUS seria 4366" • PERFUSOR COMPACT PLUS seria 14806 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34522104 HOUSING, LOWER PART (carcasa - subansamblu inferior PCP) 1 438.48 438.48 34522105 DRIVE COMPLETE PCP (Dispozitiv actionare seringa PCP) 1 1971.73 1971.73 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 • PERFUSOR COMPACT PLUS seria 14802 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34522103 HOUSING, UPPER PART PCP (Carcasa partea superioara PCP) 1 567.78 567.78 34522116 DISPLAY BOARD WITH DISPLAY CP (Afisaj LCD CP) 1 354.70 354.70 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 • PERFUSOR COMPACT PLUS seria 14813 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 LUMP SUM FOR CONSUMABLES (kit material service) 1 50.00 50.00 34522113 PROCESSOR BOARD PCP (Placa de baza PCP) 1 1255.90 1255.90 34522116 DISPLAY BOARD WITH DISPLAY CP (Afisaj LCD CP) 1 354.70 354.70 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 0 0 • INFUSOMAT COMPACT PLUS seria 4366 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIM