
Reparare imprimante HP laser jet 1005,

I.D.: 44483823

Data publicarii	08.11.19	Coduri CPV	50323200-7
Pretul estimativ:	67,50 RON - 67,50 RON		
Descriere:	Serviciul contine: -Rola preluare =15 lei+tva -Pad separare tava=17.5 lei+tva -manopera 35 lei+tva		
