
Reparatie Ecograf Phillips CX50 S/N:US71900016

I.D.: 97074485

Data publicarii	09.05.24	Coduri CPV	50421000-2 98300000-6
-----------------	----------	------------	-----------------------

Pretul estimativ: 20.461,00 RON - 20.461,00 RON

Descriere: 1. Channel Board OEM 2 - CX50 set 2. Manopera 6 ore - constatare defect - inlocuire set channel boards 2 buc - instalare soft - activare chei - testare sonde cu fantoma CIRS
