
Prestari servicii - Reparat masina de spalat

I.D.: 89527734

Data publicarii	15.11.23	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ:	378,15 RON - 378,15 RON
-------------------	-------------------------

Descriere:	Reparat masina de spalat Indesit : schimbat rezistenta
------------	--
