

Reparatie pompa Wilo Helix First V 1610

I.D.: 77863658

Data publicarii	23.01.23	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 14.205,14 RON - 14.205,14 RON

Descriere: Reparatie pompa Wilo Helix First V 1610, constand din: - schimbare rulmenti motor si rulment cuplaj, - schimbare cartus etansare, - manopera aferenta.
