
Service hidranti

I.D.: 42812708

Data publicarii	22.05.19	Coduri CPV	50413200-5
-----------------	----------	------------	------------

Pretul estimativ: 548,00 RON - 548,00 RON

Descriere: Service hidrant interior: 6 buc x 30 lei Verificat stingator tip G2: 1 buc x 10 lei Verificat stingator tip P6: 7 buc x 10 lei Teava de refulare Miami: 6 buc x48 lei
