
Servicii de reparatii instalatii racire UPS conform deviz .

I.D.: 44651117

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 18.11.19 | Coduri CPV | 50730000-1 |
|-----------------|----------|------------|------------|

Pretul estimativ: 1.945,00 RON - 1.945,00 RON

Descriere: Reparatii instalatii racier UPS spalat condensatoarele , filtre de purificare aer , remediat pierderi de Freon ,verificat cu spreieri detective pierderi : solutie spalat buc. 1 x 85 lei , Freon 3kg. x 190 lei=570 lei , spreii detector 2 x 45 lei , manopera reparatii = 1200 lei
